

CUSTOMER SUCCESS STORY

The relationship we enjoy with our customers is mutually beneficial. Many are trying new technologies in an effort to increase their plant's efficiency and improve their production. Working in arduous conditions, in very different fields, they all rely on BRELKO and our engineered solutions for a trouble-free flow of materials at transfer points.

SOLUTION : BRELKO BELT HEAD PULLEY and SECONDARY SCRAPERS.

LOCATION : TRONOX NAMAKWA SANDS, BRAND-SE-BAAI, 385KM NORTH OF CAPE TOWN, SOUTH AFRICA.




PROBLEM

Severe material carry-back and spillage on the Drive - C conveyor due to a badly grooved conveyor belt top cover as well as conveyor belting used with different thicknesses to replace badly or worn sections of the conveyor belt.

SOLUTION

To reduce spillage and material carry-back, BRELKO installed 1x E951-TT Composite Ceramic Multi-blade Head Pulley Belt Scraper and 2x E205-T Multi-blade Secondary Belt Scrapers with T3 tungsten tips and Brelko's patented Torsion Mountings to compensate for the different belt thicknesses on the Drive - C conveyor belts head/discharge chute.



RESULTS

Results of the project showed great improvement. Plant personnel report that the conveyor belt cleaning has improved and that material carry-back and spillage were almost completely eliminated. Plant personnel consider the installation as "money well spent" and...

HASSLE FREE!!!

